Rev 1120 Lin X/15 Ph	Gas coln Stre one: (30	tate of Col Conserva eet, Suite 801, D 3) 894-2100 Fa: DINSPECTI	ado 80203 2109		Subr	ection Date: <u>12/02/2019</u> nitted Date: <u>12/03/2019</u> ument Number: <u>696101630</u>		
Loc ID Inspector Name		On-Site I	nspection		<u>Statı</u>	us Summary:		
306566 Evins, Bret		2A	Doc Num:		THIS IS A FOLLOW UP INSPECTION			
Operator Information:					FOLLOW UP INSPECTION REQUIRED			
OGCC Operator Number:1	00322				X	IO FOLLOW UP INSPECTION	NREQUIRED	
Name of Operator: NOBLE ENE	RGY IN	С			<u>Find</u>	ings:		
Address: 1001 NOBLE ENERG	YWAY				11	Number of Comments		
		T)/			0	Number of Corrective Action	ns	
City: HOUSTON State: TX Zip: 77070						orrective Action Response Reque		
					F	NY CORRECTIVE ACTION(S REVIOUS INSPECTIONS TH BEEN ADDRESSED ARE STI	AT HAVE NOT	
Contact Information:								
Contact Name	Phor	Phone Email				Comment		
,			dnr_cogccengineering@state.					
,			NBL_DJBU_Inspections@nbl All Inspections energy.com					
Inspected Facilities:								
Facility ID Type	Status	Status Date	Well Cl	ass API Nur	n	Facility Name	Insp Status	
289814 WELL	ТА	11/08/2018	OW	123-249	923	SHOEMAKER A 12-1	ТА	
General Comment: This is a WELL inspection. Well(s): 1: Temporarily Abando Battery: Shut-down Inactive. Centralized Battery serves 2 Lo (Well(s): 1: Shut-In SI ; 1: Tem Refer to Field Inspection Repor for Battery / Facility, Equipment	cation II porarily t Doc. #	Ds (305631, 30 Abandoned T/	A).	n ID #305631				

		ļ	Location		
Lease Road:					
Туре	Access				
comment:	Adequate			-	
Corrective ActionL				Date:	
Overall Good:					
Signs/Marker:					
Туре					
Comment:	Refer to Field Inspection	Report Doc. #696	101631 and/or Location ID #305631		
Corrective Action:	for Battery / Facility, Equi			Date	
Туре	WELLHEAD				
Comment:					
Corrective Action:				Date	
Emergency Contact I	Number:				
Comment:				7	
Corrective Action				Date:	
Good Housekeepin	<u>q:</u>				
Туре	_				
Comment:					
Corrective Action:		Date	:		
Overall Good: 😿					
Spills:					
Туре	Area	Volume		_	_
In Containment: I	No				
Comment:					
Multilple Spills	and Releases?				
Fencing/:					
-	WELLHEAD				
	Iron panel.				
Corrective Action				Date	:
Туре					
		Report Doc. #696	101631 and/or Location ID #305631		
	for Battery / Facility, Equi	pment info.			
Corrective Action				Date:	
Equipment:					corrective date
Type: Plunger Lift	#	1			
Comment					
Corrective Action				Date:	
Type: Bradenhead	#				
Comment	: Appears plumbed to surf	ace.			

Date Run: 12/3/2019 Doc [#696101630]

Corrective Action:						Date	
Туре:			#				
Comment:			ion Report Doc. quipment info.	#696101631 and/or Loc	ation ID #305	631	
Corrective Action:		Date:					:
Tanks and Berms:							
Contents	i	# Capacity	Туре		Tank ID	SE GPS	
			CENTRALI	ZED BATTERY		40.501730,-104.4920)66

			CENTRALIZED BATT	TERY		40.501730,-1	04.49206	6
Comm	Refer to	Field Insp	y serves 2 Location IDs (30 bection Report Doc. #69610 ty, Equipment info.	05631, 306566). 01631 and/or Loo	cation ID #30	05631		
Corrective Ac	tion:						Date	
<u>Paint</u>	·							
Condition								
Other (Content)								
Other (Capacity)								
Other (Type)								
Berms								
Туре	Capacity		Permeability (Wall) Permeability (Base)		Base)	Maintenance		
Comment:								
Corrective Action:							Date	
<u>Venting:</u>								
Yes/No	NO							
Comment:	:							
Corrective Action:	:						Date:	
Flaring:								
Туре								
Comment	t:							
Corrective Action	::						Date:	

Г

				Inspected	d Facilities				
Facility ID:	289814	Type:	WELL	API Number:	123-24923	Status:	TA	Insp. Status:	TA
				<u>Idle \</u>	<u>Well</u>				
Purpose	e: 🔲 Shut Ir	n 🖸	X Temporarily	Abandoned	Reminder: EC	QUIPMENT P	RESENT/[DISCONNECTED	
<u>Cc</u>	Yell Las SI/T For For	ow LTSI t t prod: 11 A well pe m 4 doc. m 21-MIT	tag. /2015. er ALT MI Assu #401939958 in doc. #4015720	A. Production valve rance Program doc dicates TA: 02/03/2 514 MIT done: 02/1 12251464. Plugging	#02385001 (Nob 018. Approval P 7/2018. Approve	ending. ed.	2019.		
Corrective	Action:							Date:	

Reclamation - Storm Water - Pit

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment	
Gravel							
Commer	it:				•]	
Corrective Actio	n:					Date:	
Pits: 🔲 NO	SURFACE IND	ICATION OF PIT					
a			COGCC Comme	<u>ents</u>			
Comment					User	Date	
COGCC Inspect	ion Report Sum	mary:			evinsb	12/02/2019	
Location ID: 306 Well Name: Sho API: 05-123-249 Location County Weather: Clear w While there, I ob Well(s): 1: Temp Battery: Shut-do Centralized Batte (Well(s): 1: Shut Refer to Field In: for Battery / Faci	SHOEMAKER A 566 emaker A 12-1 23 : Weld County, v/ partial snow of served: orarily Abandor wn Inactive. ery serves 2 Loo In SI ; 1: Tem spection Report lity, Equipment ection, NO poss	A-66N64W /12NENE Colorado coverage from prior sto ned TA. cation IDs (305631, 30 porarily Abandoned T. Doc. #696101631 and info. ible compliance issues	06566). A). d/or Location IE				
Attached Docu							
		(https://cogcc.state.co.	.us/weblink/) ar	nd search by doc	ument number:		
<u> </u>	-	URL					
Document Num	Description OKL Site photos http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5002491						