

Inspection Photos

API: 05-061-06293

Operator: CHEMCO INC

Inspection Date: 11/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019

Inspection Photos



Photo 1. Facing southwest toward the pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019

Inspection Photos



Photo 2. The berm around the tank has been built up however, soils are loose and not compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019

Inspection Photos



Photo 3. The pipe risers at the location have been LO/TO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019

Inspection Photos



Photo 4. Facing northwest toward the wellhead. The area northeast of the well is bare of vegetation and appears to be a result of a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019

Inspection Photos



Photo 5. Facing north at the location which appears to have been impacted by a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019

Inspection Photos



Photo 6. View of aerial image shows area north of the location bare of vegetation which may be the result of a former spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 11/25/2019