

**Inspection Photos**  
**Location Name: Morrison #9-1**  
**Location ID: 320512**



**Photo 1 WH sign is on site but in disrepair**



**Photo 2 KPK rig not on secondary containment**

**Inspection Photos**  
**Location Name: Morrison #9-1**  
**Location ID: 320512**



**Photo 3 no secondary containment under rig, oil is dripping off motor and collecting on water and mud.**



**Photo 4 stained soil around well head.**