

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/02/2019

Submitted Date:

12/03/2019

Document Number:

679706395

**FIELD INSPECTION FORM**

Loc ID 335681 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10447  
Name of Operator: URSA OPERATING COMPANY LLC  
Address: 950 17TH STREET, SUITE 1900  
City: DENVER State: CO Zip: 80202

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All inspections</a>
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288986	WELL	SI	11/01/2018	GW	103-10989	BOIES C-24M-M2W	SI
293281	WELL	PR	07/01/2018	GW	103-11113	BOIES C-24M-N1	PR
293282	WELL	AL	08/09/2011	LO	103-11114	BOIES C-24M-M4	AL
293283	WELL	AL	08/08/2011	LO	103-11115	BOIES C-24M-N4	AL
293284	WELL	PR	05/28/2014	GW	103-11116	BOIES C-24M-M1	PR
293285	WELL	SI	09/01/2019	GW	103-11117	BOIES C-24M-N3	SI
293286	WELL	SI	09/01/2019	GW	103-11118	BOIES C-24M-M3	SI
293287	WELL	DG	05/07/2013	GW	103-11119	BOIES C-24M-N2	TA

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 12-2-2019 at approximately 16:20, inspector Rick Moran, conducted a routine inspection at URSA pad 24M in Rio Blanco county.

The following compliance issues were observed:

- 1) Missing well head sign at well C-24M-N2. Photo 4. Complete by 2-3-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706395.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Missing well head sign at well C-24M-N2.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/03/2020
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	Container of methanol and 1 container of MC MX 4-2311.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		39.856800,-108.348290
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		39.856800,-108.348290
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 288986 Type: WELL API Number: 103-10989 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Last recorded production December 2017.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293281 Type: WELL API Number: 103-11113 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well on plunger lift.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293282 Type: WELL API Number: 103-11114 Status: AL Insp. Status: AL

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Permit abandon 8-9-2011.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293283 Type: WELL API Number: 103-11115 Status: AL Insp. Status: AL

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Permit abandon 8-9-2011.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293284 Type: WELL API Number: 103-11116 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293285 Type: WELL API Number: 103-11117 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment: Last recorded production August 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293286 Type: WELL API Number: 103-11118 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 293287 Type: WELL API Number: 103-11119 Status: DG Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Ditches	Pass			Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706396	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003151</a>