

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2019

Submitted Date:

12/02/2019

Document Number:

694900875**FIELD INSPECTION FORM**Loc ID 335109 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257741	WELL	PR	06/20/2000	GW	045-07594	FEDERAL RMV 144-19	PR
272540	WELL	PR	11/20/2004	GW	045-10097	FEDERAL RWF 342-19	PR
272541	WELL	PR	11/22/2004	GW	045-10096	FEDERAL RWF 442-19	PR
286363	WELL	PR	08/24/2006	GW	045-12651	FEDERAL RWF 432-19	PR
286364	WELL	PR	08/24/2006	GW	045-12650	FEDERAL RWF 32-19	PR
286365	WELL	PR	08/24/2006	GW	045-12649	FEDERAL RWF 532-19	PR
286366	WELL	PR	08/24/2006	GW	045-12648	FEDERAL RWF 332-19	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 12/2/19 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP RMV 144-19, at Location # 335109 in Garfield County, Colorado.

All C/A(s) from previous inspection Document # 689301566 have been completed.

During this inspection the following possible compliance issues were observed:

- Dead man unmarked
- Fence around well heads needs maintained

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Dead Man unmarked. see photos		
Corrective Action:	Mark dead man.	Date:	12/19/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	hog panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog panel fencing around well heads need maintained. see photos		
Corrective Action:	maintain fencing around well heads.	Date:	12/19/2019

Equipment:

Type: Deadman # & Marked		# 2		corrective date
Comment:				
Corrective Action:		Date:		
Type: Plunger Lift		# 7		
Comment:				
Corrective Action:		Date:		
Type: Bird Protectors		# 6		
Comment:				
Corrective Action:		Date:		

Type: Horizontal Heated Separator	# 10	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:	centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	257741	Type:	WELL	API Number:	045-07594	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	272540	Type:	WELL	API Number:	045-10097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	272541	Type:	WELL	API Number:	045-10096	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	286363	Type:	WELL	API Number:	045-12651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	286364	Type:	WELL	API Number:	045-12650	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	286365	Type:	WELL	API Number:	045-12649	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	286366	Type:	WELL	API Number:	045-12648	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
Compaction		Ditches				
Berms		Check Dams				
Rip Rap						
Waddles						
Ditches		Rip Rap				
Check Dams		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900879	694900875	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003232