

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

687905844**FIELD INSPECTION FORM**Loc ID 312063 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259759	WELL	PR	03/15/2002	GW	067-08423	HUNGERFORD A 2	PR
298810	WELL	PR	07/11/2010	GW	067-09633	HUNGERFORD A 4	PR

**General Comment:**[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Maintained gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment spool pieces sitting on the ground next to the separator.			
Corrective Action:	Remove unused equipment per Rule 603.f.			Date: 12/18/2019
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pumpjack.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Cattle panels around tank.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels around separator and MCC.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Ancillary equipment	# 2			corrective date
Comment:	Wellheads with block valve assemblies installed.			

Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	Dual separator unit.		
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	2-4" flowlines from wellheads to dual separator. 2-2" flowlines from dual separator blowdown to produced water tank. 2-2" flowlines from dual separator dump valves to produced water tank. 2-4" flowlines from dual separator merging to 1-4" flowline to offsite dogleg. 1-2" flowline from produced water tank transfer pump to offsite gathering system.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On produced water tank vent stack.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Inside dual separator building.		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric VFD motors with MCC on both pumping units.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:	95 BBL tank with electric driven transfer pump and level control equipment installed.				
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Double-wall tank with level control equipment installed.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 259759 Type: WELL API Number: 067-08423 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 298810 Type: WELL API Number: 067-09633 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Ditches	Pass			
Ditches	Pass	Culverts	Pass			
Gradient Terraces	Pass	Gravel	Pass			
Berms	Pass	Berms	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905845	Overview photo looking south.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003324">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003324</a>
687905846	Unused equipment next to separator.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003325">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003325</a>