

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

687905847**FIELD INSPECTION FORM**Loc ID 312063 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87415**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                           | Comment                                |
|------------------|--------------|---------------------------------|--|
| Sessions, Tamara | 505-324-4145 | tsessions@logosresourcesllc.com | <a href="#">SW Inspection Reports</a>  |
| Rowley, Darren   | 505-947-4974 | drowley@logosresourcesllc.com   | <a href="#">SW Inspection Reports.</a> |
| Labowskie, Steve |              | steve.labowskie@state.co.us     | <a href="#">COGCC</a>                  |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 216458      | WELL | PR     | 02/21/1997  | GW         | 067-08064 | BONDAD 33-9 24-A | PR          |

**General Comment:**[Site inspection and equipment inventory with photos at the end of this report.](#)

| Location   |   |        |  |                 |
|--|---|--------|--|-----------------|
| <b>Lease Road:</b>                                     |   |        |  |                 |
| Type   | Access  |        |  |                 |
| comment:   | Maintained gravel access road.                |        |  |                 |
| Corrective Action                                      | L   |        |  | Date:           |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                 |
| <b>Signs/Marker:</b>                                   |   |        |  |                 |
| Type   | WELLHEAD                                      |        |  |                 |
| Comment:   | Sign posted on meter house on location.       |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type   | TANK LABELS/PLACARDS                          |        |  |                 |
| Comment:   | Labels and placards posted on fence at tank.  |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Emergency Contact Number:                              |   |        |  |                 |
| Comment:   | Contact information posted on signs.          |        |  |                 |
| Corrective Action:                                     |   |        |  | Date: _____     |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                 |
| <b>Spills:</b>   |   |        |  |                 |
| Type   | Area  | Volume |  |                 |
| In Containment: No                                     |   |        |  |                 |
| Comment:   |   |        |  |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |  |                 |
| <b>Fencing/:</b>                                       |   |        |  |                 |
| Type   | TANK BATTERY                                  |        |  |                 |
| Comment:   | T-post and hogwire around tank.               |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| <b>Equipment:</b>                                      |   |        |  |                 |
|  |   |        |  | corrective date |
| Type: Ancillary equipment                              | # 1   |        |  |                 |
| Comment:   | Wellhead with block valve assembly installed. |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type: Bird Protectors                                  | # 1   |        |  |                 |
| Comment:   | On separator stack.                           |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type: Plunger Lift                                     | # 1   |        |  |                 |
| Comment:   |   |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |
| Type: Gas Meter Run                                    | # 1   |        |  |                 |
| Comment:   |   |        |  |                 |
| Corrective Action:                                     |   |        |  | Date:           |

|                                   |  |  |       |
|-----------------------------------|--|--|-------|
| Type: Horizontal Heated Separator | # 1  |  |       |
| Comment:                          |  |  |       |
| Corrective Action:                |  |  | Date: |
| Type: Flow Line                   | # 1  |  |       |
| Comment:                          | DOMESTIC GAS TAP: 1-1" PVC FLOWLINE FROM WELLHEAD TO DOMESTIC GAS TAP SKID. GAS TAP SKID HAS BLOCK VALVES, METER AND ODORANT INJECTION INSTALLED AND IS CURRENTLY IN SERVICE.  |  |       |
| Corrective Action:                |  |  | Date: |
| Type: Flow Line                   | # 5  |  |       |
| Comment:                          | 1-2" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-1" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg. |  |       |
| Corrective Action:                |  |  | Date: |
| Type: Bradenhead                  | # 1  |  |       |
| Comment:                          | Plumbed to surface.  |  |       |
| Corrective Action:                |  |  | Date: |

**Tanks and Berms:**

| Contents           | #                                     | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---------------------------------------|----------|-----------|---------|--------|
| PRODUCED WATER     | 1                                     | 100 BBLs | PBV STEEL |         | ,      |
| Comment:           | 125 BBL tank with expanded metal top. |          |           |         |        |
| Corrective Action: |                                       |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |            |       |      |             |           |         |    |               |    |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 216458     | Type: | WELL | API Number: | 067-08064 | Status: | PR | Insp. Status: | PR |
| Producing Well       |            |       |      |             |           |         |    |               |    |
| Comment:             | Producing. |       |      |             |           |         |    |               |    |
| Corrective Action:   |            |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction        | Pass            | Compaction              | Pass                  |               |                          |         |
| Berms             | Pass            | Berms                   | Pass                  |               |                          |         |
| Gravel            | Pass            | Gravel                  | Pass                  |               |                          |         |
| Gradient Terraces | Pass            | Ditches                 | Pass                  |               |                          |         |
| Ditches           | Pass            | Culverts                | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                      | URL   |
|--------------|--|---|
| 687905848    | Overview photo looking south.                    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003326">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003326</a> |
| 687905849    | Overview domestic gas tap west edge of location. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003327">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003327</a> |