

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

695101844**FIELD INSPECTION FORM**Loc ID 311983 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergyllc.com	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergyllc.com	All Inspections
Fitzgerald, Eddie	719-859-1394	eddiefitzgerald@tcenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265527	WELL	PR	12/23/2005	GW	071-07778	GOLDEN EAGLE 28-7	PR
283708	WELL	SI	10/01/2017	GW	071-08732	GOLDEN EAGLE 28-7X	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: TWO UNMARKED UNUSED RISERS NEAR X WELLHEAD.		
Corrective Action:	REMOVE UNUSED RISER IN ACCORDANCE WITH NTO AND RULE 603.f.	Date:	02/03/2020
Type	OTHER		
Comment:	PHOTO 5: OILY IMPACTED SOIL INSIDE SOUND WALLS FOR COMPRESSOR ON ORIGINAL WELL. PHOTO 6: OILY IMPACTED SOIL NEAR X WELLHEAD. PHOTO 7: OILY IMPACTED SOIL OUTSIDE SOUND WALLS FOR ENGINE SKID FOR X WELL. PHOTO 8: OILY IMPACTED SOIL INSIDE Soud WALLS OF X WELL UNDER ENGINE SKID.		
Corrective Action:	Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907.	Date:	01/03/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 6		corrective date
Comment:	5 MARKED 1 UNMARKED.		
Corrective Action:	INSPALL GUYLINE ANCHORS IN ACCORANCE WITH RULE 1003.a.	Date:	01/03/2020
Type: Bradenhead	# 2		
Comment:	BOTH ARE PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 265527 Type: WELL API Number: 071-07778 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: Facility ID: 283708 Type: WELL API Number: 071-08732 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: LAST MIT IN 2017Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101845	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003517