

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

696101644

FIELD INSPECTION FORM

Loc ID 308461 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
MacLaren, Joe		joe.maclaren@state.co.us	
,		dnr_cogccengineering@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288971	WELL	SI	09/01/2017	OW	123-24709	COCKROFT USX A 11-2	TA

General Comment:

This is a WELL & BATTERY inspection.
Well(s): 1: Temporarily Abandoned (TA).
Battery: Abandoned & ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.507680,-104.510090
Reclamation progressing.

Follow-up to Field Inspection Report doc. #696100996 dated 06/04/2019.

Location			
Lease Road:			
	Type Access		
comment:	Adequate.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: nused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f. Corrective Action Date: 09/03/2019.</p> <p>This insp: * Unused gas meter run & riser at Abandoned Battery site NOW appears removed. See photos #3, 4.</p>		
Corrective Action:			Date:
Type	WEEDS		
Comment:	<p>Prior insp: Weeds emerging at wellsite. Consider mitigation. Refer to Rule 603.f</p> <p>This insp: * Weeds NOW appear mitigated at wellsite. See photos #1, 2.</p>		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:		corrective date
Type: Horizontal Heated Separator	# 0	
Comment: Battery: Abandoned & ALL equipment removed.		
Corrective Action:		Date:
Type: Emission Control Device	# 0	
Comment: Battery: Abandoned & ALL equipment removed.		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears plumbed to surface.		
Corrective Action:		Date:
Type: Gas Meter Run	# 0	
Comment: Battery: Abandoned & ALL equipment removed.		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment: Battery: Abandoned & ALL equipment removed.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment: Battery: Abandoned & ALL equipment removed.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 288971 Type: WELL API Number: 123-24709 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Battery Abandoned. ALL equipment removed.
COGCC records indicate last prod: 09/2015.
SI/TA well per variance Doc #401474555. (NOBLE).
Orange Decommission / Yellow LTSI tags for SI/TA status present at wellsite.
Locked-Out, Tagged Out | LOTO.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 12/03/2019 at approximately 13:25 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: COCKROFT USX A-66N64W /11NWNE Location ID: 306461 Well Name: Cockroft USX A 11-2 API: 05-123-24709 Location County: Weld County, Colorado Weather: Clear w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned (TA). Battery: Abandoned & ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.507680,-104.510090 Reclamation progressing.</p> <p>Follow-up to Field Inspection Report doc. #696100996 dated 06/04/2019. During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Unused gas meter run & riser at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. Remove unused gas meter run & riser at Abandoned Battery site. Comply w/ Rule 603.f. Corrective Action Date: 09/03/2019. * Unused gas meter run & riser at Abandoned Battery site NOW appears removed. See photos #3, 4.</p> <p>Prior Good Housekeeping COMMENT: Weeds emerging at wellsite. Consider mitigation. Refer to Rule 603.f. * Weeds NOW appear mitigated at wellsite. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101645	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003693