

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2019

Submitted Date:

11/27/2019

Document Number:

696300924**FIELD INSPECTION FORM**Loc ID 433304 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433307	WELL	PR	06/30/2014	OW	123-37579	Seventy Holes T-P-5HNB	PR
433930	WELL	PR	11/12/2013	OW	123-37855	Seventy Holes 44-41-5HNB	PR
436997	WELL	PR	05/01/2019	OW	123-39358	State Seventy Holes 31-8-17MRLNB	PR
436999	WELL	PR	03/01/2015	OW	123-39359	State Seventy Holes 41-8-17MRLNB	PR
438587	WELL	PR	02/18/2015	OW	123-40058	State Seventy Holes P-8-17MRLNB	PR
438590	WELL	PR	03/04/2015	OW	123-40059	State Seventy Holes P31-8-17MRLNC	PR
439048	WELL	PR	03/01/2015	OW	123-40287	State Seventy Holes P41-8-17MRLNC	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wells - 44-41-5HNB and T-P-5HNB are missing Wellhead Sign, see photo 6		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 12/27/2019
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Methonal Tank/Pump west of Well Pad, see photo 5		
Corrective Action:	Comply with Rule 603.f .		Date: 12/27/2019
Type	STORAGE OF SUPL		
Comment:	Unmarked Risers on the NE corner of location		
Corrective Action:	Comply with Rule 603.f .		Date: 12/02/2019
Type	OTHER		
Comment:	Stained Soil at Compressor, see photo 3		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 12/13/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:

Equipment:

Type: Horizontal Heated Separator	# 7		corrective date
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Gas Lift Meter House		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to Surface		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation Equipment		
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment: Shares berm with Crude Oil Tanks						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE			
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 60 BBLS						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment: Shares berm with Crude Oil Tanks						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	10	500 BBLS	STEEL AST		40.335440,-104.342410	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate	Walls Sufficent		Base Sufficent		Adequate
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	433307	Type:	WELL	API Number:	123-37579	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433930	Type:	WELL	API Number:	123-37855	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436997	Type:	WELL	API Number:	123-39358	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436999	Type:	WELL	API Number:	123-39359	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438587	Type:	WELL	API Number:	123-40058	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	438590	Type:	WELL	API Number:	123-40059	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	439048	Type:	WELL	API Number:	123-40287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 11/25/2019 at approximately 13:00, I, Inspector Erica Petrie, conducted a Field Inspection at Bonanza Creek Energy LLC, Seventy Holes 44-5 Pad, Location ID #433304 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained Soil at Compressor, see photo 3. Comply with Rule 907.e. Corrective Action date 12.13.2019</p> <p>Wells 44-41-5HNB and T-P-5HNB are missing the Wellhead Signs, see photo 6. Comply with Rule 210.b. Corrective Action date 12.27.2019</p> <p>Unused Chemical Tank/Pump at Westside of Wellheads, see photo 5. Comply with Rule 603.f. Corrective Action date 12.27.2019</p> <p>Unmarked 2" Risers Northeast corner of location. Refer to Rule 603.f about unmarked Risers. See Photo 4. Comply with Rule 603.f. Corrective Action date 12.02.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	11/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402250453	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5000501
696300925	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5000497