

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2019

Submitted Date:

12/04/2019

Document Number:

687905854

### FIELD INSPECTION FORM

Loc ID 325732 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215304	WELL	PR	05/13/1988	GW	067-06909	CONRAD A 1	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

<b>Location</b>				
<b>Lease Road:</b>				
	Type	Access		
	comment:	Gravel access road.		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type	WELLHEAD		
	Comment:	Sign posted at entrance to location.		
	Corrective Action:			Date:
<b>Emergency Contact Number:</b>				
	Comment:	Contact information posted on sign.		
	Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type	WELLHEAD		
	Comment:	Cattle panels around wellhead and pumpjack		
	Corrective Action:			Date:
	Type	SEPARATOR		
	Comment:	Cattle panels around separator and meter house.		
	Corrective Action:			Date:
<b>Equipment:</b>				
Type: Bradenhead	# 1			corrective date
	Comment:	PVC bradenhead access.		
	Corrective Action:			Date:
Type: Vertical Heated Separator	# 1			
	Comment:			
	Corrective Action:			Date:
Type: Bird Protectors	# 1			
	Comment:	On separator stack.		
	Corrective Action:			Date:
Type: Prime Mover	# 1			
	Comment:	Electric VFD motor and MCC installed on pumping unit.		
	Corrective Action:			Date:

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	2-3" flowlines from wellhead to separator. 1-2" flowline from separator to offsite produced water gathering system. 1-3" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215304 Type: WELL API Number: 067-06909 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Gradient Terraces	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: [Stormwater BMP's appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905855	Overview photo SE corner location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5004761">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5004761</a>