

Inspection Photos
Operator: Enduring Resources
Location/API #: 067-07769
Date: 11-14-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with intermediate wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing as described above.



Photo 4. View of reference area, comprised of sagebrush and pinyon juniper woodland, with grasses planted in openings.