

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chain link topped with barb wire X 5		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link topped with barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chain link topped with barb wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Chain link topped with barb wire		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		

Comment: Partially exposed at surface X 5		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 13	
Comment: Automation		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					
		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares containment with crude oil tanks				
Corrective Action:				
		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		,
Comment:					
Corrective Action:					
		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	315 bbl	

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>240630</u>	Type: <u>WELL</u>	API Number: <u>123-08418</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Producing Well				
Comment:	SI since 11/2018			
Corrective Action:			Date:	
Facility ID: <u>446173</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 12/5/2019 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Frank Guertner GU #1 at API #05-123-08418 in Weld County Colorado.</p> <p>While there, I observed shut in wellsite & tank battery. During this inspection no compliance issues were observed: See attached photos. Location is snow covered and muddy, the weather is overcast with light rain. No follow up on this site inspection needs to be conducted. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	12/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300686	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005813