

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | | |
|--------------------|-----------------------------------|-------|--|--|-----------------|
| | | | | | corrective date |
| Type: Plunger Lift | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | Appears to be plumbed to surface. | | | | |
| Corrective Action: | | Date: | | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 250890 Type: WELL API Number: 123-18693 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On (12/5/19) at approximately (12:40 PM), I, Inspector (Abe Serna), Conducted an on-site inspection at (TIPTON #E26-13) (Noble Energy), at (API #123-18693) in (Weld) Colorado. While there, I observed (A Shut In Well) During this inspection no compliance issues were observed: (See attached photo #1 No follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p> | sernaa | 12/05/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 698700653 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5006059 |