

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adquate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250895 Type: WELL API Number: 123-18698 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (12/5/19) at approximately (13:05 PM), I, Inspector (Abe Serna), Conducted an on-site inspection at (LYSTER #E26-15) (Noble Energy), at (API #123-18698) in (Weld) Colorado. While there, I observed (A Shut In Well) During this inspection no compliance issues were observed: (See attached photo #1 No follow up on this site inspection needs to be conducted. This is a summary of inspection report. Snow on ground.</p>	sernaa	12/05/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698700655	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5006060