

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2019

Submitted Date:

12/05/2019

Document Number:

693501864

**FIELD INSPECTION FORM**Loc ID 322888 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449620	WELL	DG	05/24/2018		123-44414	VT-LDS C4-16-18	PR

**General Comment:**

Inspected Facilities									
Facility ID:	449620	Type:	WELL	API Number:	123-44414	Status:	DG	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: None Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: Clear Temperature: 39 (F)Assisting Staff: Jason Gomez Camera #: \_\_\_\_\_☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Wellhead(s)

Comment: Witnessed Extraction dumping Upright sand pots off well heads into onsite tempory frac tank. Each video attached records when operator opens line from well head to tank and closes it. Performed inspection approx 12:30PM

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>Routine inspection with Flir camera. Videos are attached along with photos.</u>	silverr	12/05/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501865	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007033</a>
693501866	Video 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007034</a>
693501867	Video 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007035">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007035</a>
693501868	Video 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007036</a>