

# Inspection Photos

Operator: Enduring Resources  
Location/API #: 067-07759  
Date: 11-14-2019



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the eastern project area from the southeastern edge facing northward. Revegetation is progressing in portions of this slope with sand dropseed and sideoats grama.





Photo 3. View of Russian knapweed and Russian thistles debris within the eastern project area. Approximately 500 Russian knapweeds observed.





Photo 4. View of erosional rilling within the southeastern project area.





Photo 5. View of area in the southwestern project area where diverted stormwater flows deposit sediment. Stormwater controls are full of sediment and need maintenance.





Photo 6. View of the southern project area from the southeastern edge facing westward. Revegetation is progressing here.



Photo 7. View of reference area, comprised of open pinyon juniper woodland with grasses, sagebrush, and buckbrush.