

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06718
Date: 11-19-2019



Photo 1. View of the project area from the southeastern corner facing center. Soil pile in background appears to be surface owner excavation.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing in portions of the project area with mixed wheatgrasses, such as crested wheatgrass and western wheatgrass, as well as annual weeds such as cheatgrass and alyssum.



Photo 3. View of reference area, comprised of open grass field.