

# Inspection Photos

API: 05-043-40002

Operator: JAVERNICK OIL

Inspection Date: 12/4/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019

## Inspection Photos



**Photo 1.** Facing west along the access road. There are erosion issues that must be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 2.** Facing back toward the east. There is a deep erosion channel that has degraded the main access road that must be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 3.** Facing northwest toward the access road. This portion of the access road which goes to the location must be reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 4.** Facing southwest at the location there are erosion issues at the location and reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 5.** Facing back toward the east. The location has not been reclaimed and erosion is occurring.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 6.** There is equipment and debris that remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 7.** There is equipment and debris that remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 8.** Facing back toward the east. The location has not been reclaimed and erosion is occurring.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019



## Inspection Photos



**Photo 9.** There is an unused tank, pipe, and metal containment stored at the location. Unused equipment must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-043-40002 | Date: 12/4/2019