

Inspection Photos

API: 05-043-05088

Operator: JAVERNICK OIL

Inspection Date: 12/4/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 1. The erosion along the access road has not been repaired and stabilized. It appears rocks were placed at the erosion channel but are inadequate and not installed per good engineering practice. (Lat/Long:38.33276,-105.11330)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 2. View of the erosion channel along the access road. Arrow points to 3.5 ft. shovel placed in the channel to show depth and size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 3. View of rocks placed in channel which is not properly installed and is not an effective stormwater control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 4. There is erosion occurring along the road toward the location. No BMP's are installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 5. Facing northwest toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 6. It appears additional material has been placed in the embankment near the wellhead. This material is loose and not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 7. View of the western project area from the western edge facing southward. Wellhead is adjacent to an erosion channel. This area needs immediate stabilization to prevent any further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 8. Oil leakage was observed from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019

Inspection Photos



Photo 9. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-05088 | Date: 12/4/2019