

Inspection Photos

API: 05-043-40016

Operator: JAVERNICK OIL

Inspection Date: 12/4/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40016 | Date: 12/4/2019

Inspection Photos



Photo 1. Facing southwest toward the location. There is a metal pipe, cable, and wood beams. This appears to be unused equipment and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40016 | Date: 12/4/2019

Inspection Photos



Photo 2. Wood beams and metal panel are located at north side of the location. Unused equipment needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40016 | Date: 12/4/2019

Inspection Photos



Photo 3. Metal cable extends from the ground east of the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40016 | Date: 12/4/2019