

Inspection Photos

API: 05-043-06224

Operator: JAVERNICK OIL

Inspection Date: 12/4/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-043-06224 | Date: 12/4/2019

Inspection Photos



Photo 1. Facing southwest along the access road. There is vehicle rutting and erosion along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06224 | Date: 12/4/2019

Inspection Photos



Photo 2. Facing toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06224 | Date: 12/4/2019

Inspection Photos



Photo 3. Facing south along the access road. There is vehicle rutting and erosion along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06224 | Date: 12/4/2019

Inspection Photos



Photo 4. Facing toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06224 | Date: 12/4/2019

Inspection Photos



Photo 5. There are degraded and displace wattles at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06224 | Date: 12/4/2019