

Inspection Photos

API: 05-043-40014

Operator: JAVERNICK OIL

Inspection Date: 12/4/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 1. Facing north at the access road from CR 103. Access road has not been reclaimed and is bare of vegetation. Vegetation growth at left portion of the photo is undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 2. Facing northeast along the access road. The road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 3. Facing northeast along the access road. The road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 4. Facing northwest at the location which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 5. There is a metal cable that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 6. Facing back toward the southwest at the location and access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 7. There is an access road that leads northeast to the Drapper 4 well site which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 8. Facing southwest along the access road between the Hassler 24 and Drapper 4 well site. It appears soil material has been pushed over the road however, the recontouring and reclamation have not been completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019

Inspection Photos



Photo 9. The old access road begins near the Drapper 4 well site. The access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-40014 | Date: 12/4/2019