

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2019

Submitted Date:

12/06/2019

Document Number:

690101558

FIELD INSPECTION FORM

Loc ID 320660 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10156
Name of Operator: BECCA OIL LLC
Address: P O BOX 1347
City: CUSHING State: OK Zip: 74023

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Greenwood, Gina	(918) 225-2334	gina.beccaoil@gmail.com	
Sherman, Susan		susan.sherman@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204336	WELL	SI	02/01/2018	GW	005-06421	BILLINGS 1-6	EG

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.
The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline section of report.
ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities

Facility ID: 204336 Type: WELL API Number: 005-06421 Status: SI Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment:

This well is currently shut in.
 The off location flowline(s) (wellhead line) runs approximately 1885' west-southwest from the wellhead to facility/ battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Becca Oil LLC with off location flowlines. Additional inspections may be forthcoming.

Corrective Action:

Operator shall comply with the following COGCC rule:
 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101565	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007342
690101566	View E-NE from battery to well/ pump jack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007343