

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06625
Date: 11-19-2019



Photo 1. View of the project area from the southwestern corner facing center. Pump jack on the right of photo is not in use and needs to be removed.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing in portions of the project area with mixed wheatgrasses and subshrubs such as crested wheatgrass and snakeweed, as well as annual weeds such as cheatgrass and alysium.



Photos 3/4. View of waste and debris that needs to be removed, within the outer reclamation areas.



Photo 5. View of reference area, comprised of sagebrush shrubland/grass field mosaic, with grasses (crested wheatgrass) and subshrubs (snakeweed) in openings.