

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/06/2019

Submitted Date:

12/08/2019

Document Number:

679706460

FIELD INSPECTION FORM
 Loc ID 314327 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-------------------------------|---------|
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |
| Colby, Lou | | lou.colby@state.co.us | |
| Reid, Van | | van_reid@xtoenergy.com | |
| Dooling, Jessica | 970-769-6048 | Jessica_Dooling@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 228333 | WELL | TA | 05/30/2014 | GW | 103-05170 | PICEANCE CREEK UNIT-GOV 5 54-13 | PA |

General Comment:

COGCC Inspection Report Summary.

On 12-6-2019 at approximately 13:00, inspector Rick Moran, conducted a routine well inspection at XTO Energy well Piceance Creek Unit T54- 13G in Rio Blanco county.

The following compliance issues were observed:

1) No Form 6 Subsequent Report of Abandonment on file. Submit if not already sent. Complete by 1-8-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706460.

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|-----|-------------|
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 228333 Type: WELL API Number: 103-05170 Status: TA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well P&A June 2019. No equipment on location.

No Form 6 Subsequent Report of Abandonment on file. Submit if not already sent.

Corrective Action: Submit reports as per Rule 206.

Date: 01/08/2020

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action: Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 679706461 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007744 |