

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/25/2019

Submitted Date:

12/02/2019

Document Number:

688306376

FIELD INSPECTION FORM

Loc ID 437388 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26580
 Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
 Address: 925 N ELDRIDGE PARKWAY
 City: HOUSTON State: TX Zip: 77079

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Larry		larry.r.smith@conocophillips.com	
ConocoPhillips		COPColoradoReg@conocophillips.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437389	WELL	PR	05/18/2015	OW	005-07225	Prosper Farms 4-65 13-14 1H	PR

General Comment:

[Routine Inspection](#)
[No as built GPS at wellhead, no Form 4 VENT_FLARE in COGCC database](#)

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location sign at gate, AIRS Permit numbers on equipment, other safety signs posted (see attached photo)		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	See attached photo of valve leak at wellhead that is on ground < 1 quart.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	12/17/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:		corrective date
Type: FWKO	# 2	
Comment:		
Corrective Action:		Date:
Type: Flare	# 1	
Comment: pilot on		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment: see markers for buried flow line in attached photo		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment: generator next to fence on north side, propane		
Corrective Action:		Date:
Type: Horizontal Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 0	
Comment:		
Corrective Action:		Date:
Type: VRT	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment: pilot on		
Corrective Action:		Date:
Type: VRU	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: 1 psi, casing 105 psi, tubing 86 psi		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: electric		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment: safety shut down		
Corrective Action:		Date:

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same metal berms as crude oil tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:	Date:
--------------------	-------

Location Construction

Location ID: 437389 CDP: _____

Comment:

Corrective Action: **Date:** _____

Form 2A COAs:

Comment:

Corrective Action: **Date:** _____

Wildlife BMPs:

Comment:

Corrective Action: **Date:** _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 437389 Type: WELL API Number: 005-07225 Status: PR Insp. Status: PR

Producing Well

Comment: [PR. Sep 2019 production reported to COGCC database.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402251309	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5001837
688306416	Burlington Resources Prosper Farms 4-65 13-14 1H	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5001826