

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2019

Submitted Date:

12/09/2019

Document Number:

687905872

FIELD INSPECTION FORM

Loc ID 333833 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 22 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Roy, Catherine		catherine.roy@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215045	WELL	PR	12/15/1982	GW	067-06650	ROBERTSON 19-01 1	PR
216417	WELL	PR	10/02/2014	GW	067-08023	STATE COM BZ 2	PR

General Comment:

Site inspection and equipment inventory with photos at the end of this report. This inspection does not alleviate from prior corrective actions from previous inspection Doc# 680603221 submitted on 10/29/2018.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road through locked gate.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on signs.		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused catalytic heater stored in meter house and unused telemetry/antenna mounting pole and cement pad sitting inside cattle panels south of meter house.		
Corrective Action:	Remove unused equipment per Rule 603.f.		Date: <u>01/09/2020</u>
Type	DEBRIS		
Comment:	Kochia plants up to three feet tall observed on the well pad. These are drying and are debris. CA from previous inspection Doc# 680603221 not completed. CA date from previous inspection retained to show time out of compliance.		
Corrective Action:	Remove kochia debris.		Date: <u>11/30/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panels around wellhead.		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 0		corrective date

Comment:	4 anchors observed, 2 with missing or down carsonite markers.		Date:	12/23/2019
Corrective Action:	Mark anchors per Rule 1003.a.			
Type: Prime Mover	# 2			
Comment:	Electric VFD motors with MCC located at LRP's.		Date:	
Corrective Action:				
Type: Flow Line	# 6			
Comment:	2-3" flowlines from wellhead to separator. 1-3" flowline from separator bypass to downstream tie-in at meter house. 1-2" flowline from separator dump valve to produced water tank and also to offsite produced water gathering system. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite dogleg.		Date:	
Corrective Action:				
Type: Bird Protectors	# 1			
Comment:	On separator stack.		Date:	
Corrective Action:				
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:				
Type: Horizontal Heated Separator	# 1			
Comment:			Date:	
Corrective Action:				
Type: Pump Jack	# 2			
Comment:	Linear rod pumps installed.		Date:	
Corrective Action:				
Type: Bradenhead	# 2			
Comment:	PVC bradenhead access.		Date:	
Corrective Action:				
Type: Ancillary equipment	# 2			
Comment:	Wellheads with block valve assemblies installed.		Date:	
Corrective Action:				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		,
Comment:	21 BBL tank.				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215045 Type: WELL API Number: 067-06650 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 216417 Type: WELL API Number: 067-08023 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass					
Ditches	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905873	Unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008783
687905874	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008784
687905875	Kochia debris on wellpad.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008785
687905876	Kochia debris on wellpad.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008786
687905877	Down or missing anchor markers.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008787