

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2019

Submitted Date:

12/09/2019

Document Number:

687905878**FIELD INSPECTION FORM**Loc ID 306795 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roy, Catherine		catherine.roy@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266039	WELL	PR	02/06/2003	GW	067-08778	ROBERTSON 19-01 2	PR

General Comment:

Site inspection and equipment inventory with photos at the end of this report. Follow up inspection to doc# 693900566 submitted on 07/25/2019.

Location				
Lease Road:				
Type	Access			
comment:	Gravel road access through locked gate.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted on cattle panels at wellhead.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on tank and also on sign on cattle panels around tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Cattle panels around separator and meter house.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Cattle panels around tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and genset.			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	OilLift natural gas powered Genset with x-former installed at wellhead for onsite electricity.			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Linear Rod Pump installed.			
Corrective Action:				Date:

Type: Flow Line	# 6	
Comment:	1-3" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to produced water tank and also to offsite gathering system. 1-1" flowline from wellhead to Genset fuel gas. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	PVC bradenhead access.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	Previous inspection Doc# 693900566 indicated unmarked rig anchor in southern project area. Rig anchors all all currently marked at time of inspection and CA has been satisfied.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:	On separator stack.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Wellhead with block valve assembly installed.	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric VFD motor and MCC installed on LRP.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Venting:</u>		
Yes/No	NO	
Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Flaring:</u>		
Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities				
Facility ID: 266039	Type: WELL	API Number: 067-08778	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass	Culverts	Pass			
Berms	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention for Genset oil tank.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905879	Overview photo looking West.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008788