

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2019

Submitted Date:

12/09/2019

Document Number:

687905880

FIELD INSPECTION FORM

Loc ID 333841 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All | | SanJuanCOGCC@bp.com | All Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 215596 | WELL | PR | 12/13/1989 | GW | 067-07201 | STATE CB 1 | PR |

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel access road off state Hwy. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance to location. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Labels and placards posted on tank and on containment ring. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | Contact information posted on signs. | | Date: _____ |
| Corrective Action: | | | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Cattle panels around tank. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Cattle panels around wellhead. | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Cattle panels around weparator and meter house. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Gas Meter Run | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead with block valve assembly installed. | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------------|--|-------|
| Type: Ancillary equipment | # 1 | |
| Comment: | Injection Well (EPA) 03 067 - 08022 has PA well marker installed. | |
| Corrective Action: | | Date: |
| Type: Flow Line | # 6 | |
| Comment: | 1-3" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-3" flowline from separator to meter house. 1-3" flowline from meter house to offsite dogleg. | |
| Corrective Action: | | Date: |
| Type: Vertical Heated Separator | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 1 | |
| Comment: | PVC bradenhead access. | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 1 | |
| Comment: | On separator stack. | |
| Corrective Action: | | Date: |
| Type: Deadman # & Marked | # 6 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--------------|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | |
| Comment: | 95 BBL tank. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 215596 Type: WELL API Number: 067-07201 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| Ditches | Pass | Gravel | Pass | | | |
| Compaction | Pass | Ditches | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 687905881 | Overview photo looking North. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008789 |