

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/06/2019

Submitted Date:

12/09/2019

Document Number:

679706470

FIELD INSPECTION FORM

Loc ID 335878 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORTH WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272583	WELL	PR	02/01/2013	GW	103-10441	PICEANCE CREEK UNIT T78X-12G1	PR
272910	WELL	PR	02/01/2013	GW	103-10457	PICEANCE CREEK UNIT T78X-12G3	PR
273595	WELL	SI	09/01/2019	GW	103-10479	PICEANCE CREEK UNIT T78X-12G4	SI

General Comment:

[COGCC Inspection Report Summary.](#)

On 12-6-2019 at approximately 13:40, inspector Rick Moran, conducted a routine well inspection at XTO Energy pad Piceance Creek Unit T78X-12G Piceance Creek in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 679706470.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Ancillary equipment	# 1		
Comment:	Container of SCI-8760 with secondary containment.		
Corrective Action:		Date:	
Other	# 1		
Comment:	Well manifold.		
Corrective Action:		Date:	
Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 3		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 272583 Type: WELL API Number: 103-10441 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift.

Corrective Action:

Date:

Facility ID: 272910 Type: WELL API Number: 103-10457 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift.

Corrective Action:

Date:

Facility ID: 273595 Type: WELL API Number: 103-10479 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Last recorded production August 2019.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass			Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706471	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5008850