

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06560
Date: 11-19-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with smooth brome, sagebrush, and snakeweed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area, comprised of sagebrush shrubland/grassland mosaic with sagebrush, pinyon and juniper trees, smooth brome, and snakeweed.