

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06645
Date: 11-19-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing, largely with crested wheatgrass.



Photo 3. View of spotted knapweeds within the western project area.



Photo 4. View of musk thistles along the fenceline at the tank battery.



Photo 5. View of reference area, largely comprised of crested wheatgrass, and other wheatgrasses largely in dormant vegetative condition.