

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate x 2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Barb wire		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Automation		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 429490 Type: WELL API Number: 123-35810 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

Facility ID: 429491 Type: WELL API Number: 123-35811 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 12/9/2019 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Creston Peak Resources location:</p> <p style="text-align: right;">Echeverria 2A-2H & Echeverria 2B-2H at Location #429488 in Weld County Colorado.</p> <p>While there, I observed a PR wellsite. During this inspection no compliance issues were observed: See location photos. Location is wet and muddy with some snow, weather is partly cloudy. No follow up on this site inspection needs to be conducted. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	12/09/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300695	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009060