

# Construction and Stormwater Inspection

December 9, 2019

Operator: CONFLUENCE DJ LLC- #10518

Location ID: 453535

Inspection Document #: 697500886

Weld County, CO

SESE Section 31 T1N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Missouri /31  
Location ID: 453535



**Photo 1.** Photo taken from the entrance of the location off CR 2, facing West. Photo illustrates sediment track out onto CR 2. The current vehicle tracking device BMPs are not adequate to be in compliance with Rule 1002.f.(2)F.



Inspection Photos  
Location Name: Missouri /31  
Location ID: 453535



**Photo 2.** Photo taken from the entrance of the location, facing North. The current vehicle tracking device BMPs are not adequate to be in compliance with Rule 1002.f.(2)F.



Inspection Photos  
Location Name: Missouri /31  
Location ID: 453535



**Photo 3.** Photo taken from the location, facing South. Photo illustrates the current muddy conditions. Operator has not plated the location making it susceptible to muddy conditions and continued track out.



Inspection Photos  
Location Name: Missouri /31  
Location ID: 453535



**Photo 4.** Photo taken from the southern location, facing East. Photo illustrates a ditch and berm BMP that has been installed around the entire perimeter of location.



**Photo 5.** Photo taken from the southeastern location, facing North. See comments under Photo 4.



Inspection Photos  
Location Name: Missouri /31  
Location ID: 453535



**Photo 6.** Photo taken from the northern location, facing West. See comments under Photo 4.

Photo also illustrates the northern topsoil stockpile which has been temporarily stabilized with equipment tracking.



**Photo 7.** Photo taken from the northwestern location, facing West. Photo illustrates a sediment trap BMP.



Inspection Photos  
Location Name: Missouri /31  
Location ID: 453535



**Photo 8.** Photo taken from the northwestern location, facing South. See comments under Photo 4.

Photo also illustrates the western topsoil stockpile which has been temporarily stabilized with equipment tracking.



**Photo 9.** Photo taken from the southwestern location, facing East. Photo illustrates a sediment trap BMP.