

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06821
Date: 11-19-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of oily material and stained soils around pump jack.



Photo 3. View of wellhead. Stained soils present around the well head.



Photo 4. View of the western project area from the southwestern corner facing northward. Vegetation is largely in a dormant condition at this time, largely comprised of mixed wheatgrasses, snakeweed, sagebrush, and annual weeds.



Photo 5. View of reference area, largely comprised of sagebrush, mixed wheatgrasses, and annual weeds.