

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/10/2019

Submitted Date:

12/11/2019

Document Number:

696101684

FIELD INSPECTION FORM
 Loc ID 306088 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
James, Brian		bjames@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285406	WELL	PR	09/01/2018	GW	123-23967	SIEBRING CNE-32	SI

General Comment:

This is a WELL inspection.

Well(s): 1 ; Shut-In | SI.

Battery: Active

Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267).

(Well(s): 5 ; 2: Producing | PR ; 1: Shut-In | SI ; 2:Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696101432 dated 10/17/2019.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<p>Prior insp: Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019.</p> <p>This insp: * Emergency number NOW posted at wellsite. See photos #1, 2.</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Plunger Lift	# 1			

Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.363010,-104.450910	
Comment:	Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). Refer to Field Inspection Report doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285406	Type:	WELL	API Number:	123-23967	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: PRODUCTION RECORDS									
Comment: Shut-In SI. Observed production valves shut.									
Corrective Action: Date:									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 12/10/2019 at approximately 13:06 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: SIEBRING-65N63W /32NWNE Location ID: 306088 Well Name: Siebring CNE-32 API: 05-123-23967 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Active</p> <p>Centralized Battery serves 5 Location IDs (332237, 306088, 332148, 332236, 332267). (Well(s): 5 ; 2: Producing PR ; 1: Shut-In SI ; 2: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101430 and/or Location ID #332237 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696101432 dated 10/17/2019.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Emergency number NOT posted at wellsite. Refer to Rule 210.b. (30 Days). Post Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/18/2019. * Emergency number NOW posted at wellsite. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/11/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101685	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010552