

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402042837

Date Received:  
05/14/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
		Cogcc.inspections@crestonepr.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401919  
Inspection Date: 04/18/2019 FIR Submit Date: 04/18/2019 FIR Status:

Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Company Number: 10633  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 336337

Location Name: RAY NELSON-62N68W Number: 32SWSW County:  
Qtrqr: SWS Sec: 32 Twp: 2N Range: 68W Meridian: 6  
W  
Latitude: 40.090469 Longitude: -105.033071

FACILITY - API Number: 05-123- -00 Facility ID: 336337

Facility Name: RAY NELSON-62N68W Number: 32SWSW  
Qtrqr: SWS Sec: 32 Twp: 2N Range: 68W Meridian: 6  
W  
Latitude: 40.090469 Longitude: -105.033071

CORRECTIVE ACTIIONS:

1  CA# 124402

Corrective Action: Comply with rule 603 f Date: 05/18/2019

Response: CA COMPLETED Date of Completion: 05/13/2019

Operator Comment: Equipment has been removed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 124403

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/18/2019

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator  
Comment: Leak was repaired.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3  CA# 124404

Corrective Action: Comply with Rule 603.f .  
For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.

Date: 05/18/2019

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator  
Comment: Risers have been labeled and LOTO.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

4  CA# 124405

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 05/18/2019

Response: CA COMPLETED

Date of Completion: 04/19/2019

Operator  
Comment: Soil has been removed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: John Gardner

Signed: \_\_\_\_\_

Title: Env Supervisor

Date: 5/14/2019 9:49:14 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
402042837	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files