

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2019

Submitted Date:

12/11/2019

Document Number:

696101693

FIELD INSPECTION FORM

Loc ID 332268 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10071
 Name of Operator: HIGHPOINT OPERATING CORPORATION
 Address: 555 17TH ST STE 3700
 City: DENVER State: CO Zip: 80202

Findings:
12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Tim		tbrown@hpres.com	MIT
,		dnr_cogccengineering@state.co.us	
James, Brian		bjames@hpres.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271460	WELL	TA	07/11/2017	GW	123-22064	VAN WYKE 22-32	TA

General Comment:

This is a WELL inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (332695, 332268).
 (Well(s): 3: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696101446 dated 10/21/2019.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Prior insp: Invalid Operator name posted at Van Wyke 22-32 wellsite. Refer to Rule 210.b. (60 Days). Post Valid Operator name at Van Wyke 22-32 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/23/2019. This insp: * Valid Operator name NOW posted at Van Wyke 22-32 wellsite. See photos #1, 2.		
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		Date:
Corrective Action:		

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type:	#		

Comment:	Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.362840,-104.463810
Comment:	Centralized Battery serves 2 Location IDs (332695, 332268). Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 271460 Type: WELL API Number: 123-22064 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: **Prior insp:**
No Current MIT on record. Refer to Rule 319.b.
Refer to WARNING Letter Doc #401966987 dated 03/11/2019.
Corrective Action Date: 06/30/2019. (WARNING Letter).

This insp:
Temporarily Abandoned | TA.
Form 4 doc #401618993 indicates TA w/ bridge plug. Date:05/31/2017. Approval Pending.
Form 42 MIT-Notice doc #402225447 indicates planned MIT date:11/08/2019.
Form 21-MIT doc #402240337 indicates MIT done: 11/08/2019. Approval Pending.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 12/10/2019 at approximately 14:11 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: VAN WYKE-65N63W /32SENW Location ID: 332268 Well Name: Van Wyke 22-32 API: 05-123-22064 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Shut-down Inactive.</p> <p>Centralized Battery serves 2 Location IDs (332695, 332268). (Well(s): 3: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696101446 dated 10/21/2019. During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Invalid Operator name posted at Van Wyke 22-32 wellsite. Refer to Rule 210.b. (60 Days). Post Valid Operator name at Van Wyke 22-32 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/23/2019. * Valid Operator name NOW posted at Van Wyke 22-32 wellsite. See photos #1, 2.</p> <p>2.) Delinquent MIT: Van Wyke 22-32 Form 4 doc #401618993 indicates TA w/ bridge plug. Date: 05/31/2017. Form 42 MIT-Notice doc #402187611 indicates planned MIT date:10/16/2019. No Current MIT on record. Refer to Rule 319.b. Refer to WARNING Letter Doc #401966987 dated 03/11/2019. Corrective Action Date: 06/30/2019. (WARNING Letter). * Form 21-MIT doc #402240337 indicates MIT done: 11/08/2019. Approval Pending.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101694	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010712