

**Inspection Photos**  
**Operator: Williford Resources**  
**Location/API #: 067-06557**  
**Date: 11-19-2019**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is largely in a dormant condition at this time, but largely comprised of mixed wheatgrasses, snakeweed, sagebrush, and annual weeds.



Photo 3. View of unused tubing stored within the project area.



Photo 4. View of unused tank within the northeastern project area. Russian knapweeds are growing around the tank.



Photo 5. View of more tubing stored near the project area.



Photo 6. View of more unused tubing stored north of the project area.



Photo 7. View of reference area, largely comprised of sagebrush, mixed wheatgrasses, and annual weeds such as yellow tumbled mustard and *Alyssum simplex*.