

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2019

Submitted Date:

12/04/2019

Document Number:

699300655**FIELD INSPECTION FORM**Loc ID 321421 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	<a href="#">All Inspectors</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206919	WELL	PR	02/01/2015	GW	013-06414	ANDERSON MB 33-5	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	DEBRIS	
Comment:	Dead weeds around WH	
Corrective Action:	Comply with Rule 603.f	Date: 12/11/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	AG fence	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	

<b>Venting:</b>		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>	
Type	

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 206919 Type: WELL API Number: 013-06414 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 12/4/2019 at approximately 0900 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at an Extraction Oil &amp; Gas Inc.:</p> <p style="text-align: right;">Anderson MB 33-5 at API #05-013-06414 in Boulder County Colorado.</p> <p>While there, I observed producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>603.f Debris: Dead weeds around wellhead, CA date 12/11/2019 see photos 1 &amp; 2.</p> <p>Location is muddy with some snow &amp; the weather is overcast.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	12/04/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402254622	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005196">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005196</a>
699300656	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005190">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5005190</a>