

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316




Photo #0223 photo from SW corner of location.




Photo #0227 stained gravel under drain valve.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #0225 Multiple holes in tank containment liner.**



**Photo #0226 Multiple holes in tank containment liner.**