

Interim Reclamation and Stormwater Inspection

December 9, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 453447

Inspection Document #: 697500900

Weld County, CO

SESW Section 13 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: AZUL /13-18HZ
Location ID: 453447



Photo 1. Photo taken from the southern location, facing West. Photo illustrates Operator has performed Interim Reclamation activities with the evidence of drill rows, straw crimped mulch and germination.

Inspection Photos
Location Name: AZUL /13-18HZ
Location ID: 453447



Photo 2. Photo taken from the southern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: AZUL /13-18HZ
Location ID: 453447



Photo 3. Photo taken from the central location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: AZUL /13-18HZ
Location ID: 453447



Photo 4. Photo taken from the central location, facing North. See comments under Photo 1. Also, photo illustrates perimeter ditch and berm BMP installed along the eastern location that appears to be in proper functioning condition at the time of this inspection.