

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:	Prior CA for leaking packing has been addressed, well is being plugged.			
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 244751 Type: WELL API Number: 123-12546 Status: SI Insp. Status: WK

Workover

Comment: Hold safety meeting, MIRU Cutters e-line, RIH with 4 1/2" 10K CIBP and set @ 6843' KB, POOH with setting tool, RIH with dump bailer and spot 2 sxs of cement slurry on top of CIBP, POOH with dump bailer, RD e-line.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696501295	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012366