

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/12/2019

Submitted Date:

12/12/2019

Document Number:

698700673

**FIELD INSPECTION FORM**
 Loc ID 426222 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                                  | Comment         |
|--------------|-------|--|-----------------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | All Inspections |
| Kraich, Adam |       | adam.kraich@state.co.us                |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 426214      | WELL | PR     | 10/09/2012  | OW         | 123-34611 | MANSFIELD E 36-65HN | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Panels   |       |  |
| Corrective Action: |          | Date: |  |

|                    |                                   |       |                 |
|--------------------|-----------------------------------|-------|-----------------|
| <b>Equipment:</b>  |                                   |       | corrective date |
| Type: Bradenhead   | # 1                               |       |                 |
| Comment:           | Appears to be plumbed to surface. |       |                 |
| Corrective Action: |                                   | Date: |                 |
| Type: Plunger Lift | # 1                               |       |                 |
| Comment:           |                                   |       |                 |
| Corrective Action: |                                   | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 426214 Type: WELL API Number: 123-34611 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On (12/12/19) at approximately (14:48 PM), I, Abe Serna,</p> <p>Conducted an on-site inspection at (Mansfield #36-65HN),</p> <p>API#(123-34611) in (Weld County) Colorado.</p> <p>While there, I observed (a Producing)</p> <p>No follow up on this site inspection needs to be conducted to</p> <p>This is a summary of inspection report.</p> <p>Continuing Inspector Training</p> | sernaa | 12/12/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 698700674    | Photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012430</a> |