

Inspection Photos
Operator: BP America
Location/API #: 067-09031
Date: 12-10-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is in a dormant vegetative condition, and appears to be progressing with crop grasses similar to surrounding grass field.



Photo 4. View of reference area, comprised of irrigated crop field.