

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2019

Submitted Date:

12/13/2019

Document Number:

690101589

FIELD INSPECTION FORM

Loc ID 320314 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Davison, Jason		jdavidson@gwp.com	
		cogccinspections@gwogco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203433	WELL	SI	05/01/2019	GW	001-08992	N COLORADO 44-13 9	EG
469660	SPILL OR RELEASE	CL	11/25/2019		-	North Colorado 44-13-9	EG

General Comment:

Engineering Integrity inspection performed on December 12th, 2019 in response to initial form 19 spill report Doc #402258474 received by COGCC on 12/10/2019 that outlines: Potential impacts to soil and shallow groundwater were discovered during removal of a produced water vault associated with plugging and abandonment of the facility.

Details of observations made during this field inspection are located in the flowline and comment sections of this report. Photos uploaded.

Inspected Facilities			
Facility ID: <u>203433</u>	Type: <u>WELL</u>	API Number: <u>001-08992</u>	Status: <u>SI</u> Insp. Status: <u>EG</u>
Facility ID: <u>469660</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u> Insp. Status: <u>EG</u>
Flowline			
#1	Type: <u>Non-Well Site</u>	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Non-Well Site</u>	Size: <u>2"</u>	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	Well (North Colorado 44-13-9) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402240334 received on 11/15/2019. No GWOG or contract personnel were on location at the time of this field inspection. Excavation and remediation work is in progress/ nearing completion. Per communications with GWOG personnel, the 2" flowlines (off location-wellhead/ facility lines) have been removed. No flowline risers were observed during this field inspection at the wellhead or facility/ battery locations (located across Garfield st approx. 740' east of (PA) well).		<u>Date:</u>
<u>Corrective Action:</u>			

COGCC Comments		
Comment	User	Date
*Note: There is (1) disconnected/ out of service gas gathering meter run (DCP Midstream) approximately 740' east of the (PA) well: The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.	maclarej	12/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101590	View of (PA) well/ location (to west from Garfield St)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012818
690101591	Out of service meter run; flowlines removed (view west)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012819