

Inspection Photos
Operator: BP America
Location/API #: 067-09938
Date: 12-13-2019



Photo 1. View of the project area from the southwestern corner facing center. Russian thistle debris in background needs to be removed.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as crested and intermediate wheatgrass. These non-native species are not representative of reference area vegetation.




Photo 3. View of Russian knapweed infestation along the edge of the access road. Thousands of individuals observed.



Photo 4. View of the musk thistles in post-flowering condition, growing along the access road.



Photo 5. View of reference area, comprised of pinyon juniper woodland with understory dominated by sagebrush and Indian ricegrass.