

Inspection Photos  
Operator: BP America  
Location/API #: 067-06640  
Date: 12-13-2019



Photo 1. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as sand dropseed and rubber rabbitbrush.





Photo 2. View of the southern project area from the well pad entrance facing westward.





Photo 3. View of area within the northwestern well pad, where gravel and sediment washes off of the well pad into diversion channel. BMPs are full of gravel and sediment and do not appear to be the appropriate BMP for this area.





Photo 4. Another view of the northwestern project area facing northward. It appears well pad gravel and sediment washes off of the well pad into the diversion where BMPs are filling with sediment.





Photo 5. View of Russian knapweeds within the southeastern project area.





Photo 6. View of reference area, comprised of open pinyon juniper woodland with understory dominated by sagebrush and Indian ricegrass.