

Inspection Photos
Location Name: Carmin USX CC 05-17D
Location ID: 331510



Colorado Oil and Gas Conservation Commission
40.33956, -104.45431, 4696.8ft, 245°
12/16/2019 10:23:15 AM



Colorado Oil and Gas Conservation Commission
40.33955, -104.45431, 4589.8ft, 232°
12/16/2019 10:23:24 AM

Photo #1 Wells

Photo #2 Wellhead, Sign & Trash

Inspection Photos
Location Name: Carmin USX CC 05-17D
Location ID: 331510



Photo #3 Well, Sign, & Variance Tag

Photo #4 Well, Sign, & Variance Tag

Inspection Photos
Location Name: Carmin USX CC 05-17D
Location ID: 331510



Colorado Oil and Gas Conservation Commission
40.33955, -104.45449, 4593.9ft, 207°
12/16/2019 10:24:24 AM



Colorado Oil and Gas Conservation Commission
40.33566, -104.45313, 4627.5ft, 321°
12/16/2019 09:55:26 AM


Photo #5 Well, Sign, & Variance Tag

Photo #6 Separators, ECD's & Meter Runs

Inspection Photos
Location Name: Carmin USX CC 05-17D
Location ID: 331510



Colorado Oil and Gas Conservation Commission
40.33556, -104.45305, 4630.2ft, 247°
12/16/2019 09:53:20 AM



360
Colorado Oil and Gas Conservation Commission
40.33549, -104.45317, 4626.3ft, 249°
12/16/2019 09:53:41 AM

Photo #7 Tank Battery

Photo #8 Faded Capacity Label

Inspection Photos
Location Name: Carmin USX CC 05-17D
Location ID: 331510



Photo #9 Missing Capacity Label

Photo #10 Water Tank/ Inadequate berms

Inspection Photos
Location Name: Carmin USX CC 05-17D
Location ID: 331510



Photo #11 Inadequate berms

Photo #12 Inadequate berms